Vice President - Nuclear Operations

PPL Susquehanna, LLC 769 Salem Boulevard Berwick, PA 18603 Tel. 570.542.3959 Fax 570.542-1504 rasaccone@pplweb.com



JAN 24 2007

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Stop OP1-17 Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 50-387/2006-006-00 PLA-6151

Docket 50-387

Attached is Licensee Event Report 50-387/2006-006-00. This event was determined to be reportable per 10 CFR 50.73(a)(2)(iv)(A) for an unplanned actuation of systems used to mitigate the consequences of significant events. On November 25, 2006, Susquehanna Unit 1 automatically scrammed in response to a generator lockout which was caused by a loss of generator field.

There were no actual consequences to the health and safety of the public as a result of this event.

No new regulatory commitments have been created through issuance of this report.

Robert A. Saccone

Vice President – Nuclear Operations

Attachment

cc:

Mr. C. R. Welch, NRC Sr. Resident Inspector

Mr. S. J. Collins, NRC Regional Administrator, Region I

Mr. R. R. Janati, DEP/BRP

Mr. R. Osborne, Allegheny Electric

IE22

~~~~																				
NRC FORM	1 366	; U	J.S. NUCLEAR REGULATORY								BOVED F	SY OMB	NO 3	150-010	1		EXP	IRES:	06/30/2007	
COMMISSION							_	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 06/30/2007 Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory												
		LI	CENS	EE EV	ENT I	REF	PORT	(LER	1)	Com	mission, 1	Washing	ton, D0	20555-	0001, o	r by intern Office of	et e-ma	il to	,	
				everse fo				•	´	Regu	ulatory Affa	airs, NEO	B-1020	2, (3150-	0104), C	Office of Ma	nagem	ent an	d Budget,	
										Wash	hington, [	OC 20503	3. If a	means u	sed to in	npose an	nforma	tion co	llection	
of digits/characters for each block)										does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.										
1. FACILITY NAME Susquehanna Steam Electric Sta							Station	Station – Unit 1			2. DOCKET NUMBER 3. PA					AGE				
			•						,			05000387					1 OF 3			
4. TITLE Automatic Scram due to Main Generator Lockout																				
5. EVE	NT [	DATE	6. LER NUMBER				7. REPORT DATE			8. OTHER FACILITIES INV						OLVED				
MONTH D	ΑΥ	YEAR	YEAR	SEQUEN'		EV IO.	MONTH	DAY	YEAR	F	ACILIT	YNAME					DOC		NUMBER 000	
											ACILIT	Y NAME					DOC		NUMBER	
11 2	25	2006	2006	006		00	1	24	2007									050	000	
9. OPERATING MODE 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply																				
1			20.2201(b) 20.2203(a)(3)(i)						a)(3)(i)	$\square$ 50.73(a)(2)(i)(C) $\square$ 50.73(a)(2)(vii)										
10. POWER LEVEL 100%			☐ 20.2201(d). ☐ 20.2203(a)(1). ☐ 20.2203(a)(2)(i). ☐ 20.2203(a)(2)(ii). ☐ 20.2203(a)(2)(iii). ☐ 20.2203(a)(2)(iv). ☐ 20.2203(a)(2)(v). ☐ 20.2203(a)(2)(v).				☐ 20.2203(a)(3)(ii) ☐ 20.2203(a)(4) ☐ 50.36(c)(1)(i)(A) ☐ 50.36(c)(1)(ii)(A) ☐ 50.36(c)(2) ☐ 50.46(a)(3)(ii) ☐ 50.73(a)(2)(i)(A) ☐ 50.73(a)(2)(i)(B)			☐ 50.73(a)(2)(ii)(B) ☐ 50.73(a)(2)(iii) ☐ ☐ 50.73(a)(2)(iii) ☐ ☐ 50.73(a)(2)(iv)(A) ☐ 50.73(a)(2)(v)(B) ☐ 50.73(a)(2)(v)(C) ☐ 50.73(a)(2)(v)(C) ☐ 50.73(a)(2)(v)(D) · Sp					50 50 50 73 73 01 Speci	0.73(a)(2)(viii)(A) 0.73(a)(2)(viii)(B) 0.73(a)(2)(ix)(A) 0.73(a)(2)(x) 3.71(a)(4) 3.71(a)(5) DTHER Voluntary Report cify in Abstract below 1 NRC Form 366A				
																or in	NRC F	orm 3	366A	
						12.	LICENSE	EE CON	TACT F	OR	THIS LE	ER								
FACILITY NAM														TE	LEPHO	NE NUMER	(Include	Area C	ode)	
Eric J. N	/lille	r – Nucle	ar Regu	ulatory A	ffairs											570-54	2-332	1		
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT																				
CAUSE		SYSTEM	1 СОМ	COMPONENT MANU- FACTUREF		-	REPORTABLE TO EPIX		CAL	CAUSE		SYSTEM		COMPONENT		MANU- FACTURER		REPORTABLE TO EPIX		
14. SUPPLEMENTAL REPORT EXPECTED									1	15. EXPECTED MONT				MONTH	D	 АҮ	YEAR			
			es, complete 15. EXPECTED SUBMISSION DATE)						NO SUBMISSION DATE			1								
ABSTRACT	(Limit	t to 1400 spac	ces; i.e., ap	proximately	15 single	space	ed typewritte	en lines)			· · · · · · · · · · · · · · · · · · ·									

On November 25, 2006 with Susquehanna Unit 1 in Mode 1 at 100%, the reactor automatically scrammed as a result of a turbine trip in response to a generator lockout. The main generator automatic voltage regulation circuitry did not positively respond to changes to the offsite grid which resulted in a loss of generator field and a subsequent unit shutdown. Investigation suggests that improper active/reactive current compensator (ARCC) settings in the automatic voltage regulation system were a probable contributor to this shutdown. In addition, a decision to forego modification of the automatic voltage regulators in a manner described in GE TIL 961-3, may also have contributed to the inability of Susquehanna's units to adequately respond to the grid disturbances. At the root of these suggested contributors to the shutdown, it has become apparent that there is a lack of sufficient, in-house understanding of the automatic voltage regulator response to a changing grid configuration. Until planned corrective actions are sufficiently completed, the Unit 1 Main Generator Voltage Regulator is being maintained in manual to ensure continued station operation during grid disturbances. In response to this event, the station intends to implement measures to ensure appropriate personnel fully understand generator control and protection schemes. Appropriate ARCC setting changes will also be established. Additionally, General Electric Technical Information Letter 961-3 will be re-evaluated and implemented if such action will enhance the unit's ability to respond correctly to grid disturbances.

This situation is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an unplanned actuation of a system designed to mitigate the consequences of a significant event. There were no actual adverse consequences to the health and safety of the public as a result of this event.

#### NRC FORM 366A

(1-2001)

#### U.S. NUCLEAR REGULATORY COMMISSION

## LICENSEE EVENT REPORT (LER)

		• (-	,			
1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE		
Susquehanna Steam Electric Station – Unit 1	05000387	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 3	
,	0000007	2006	- 006	- 00	2003	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

### **EVENT DESCRIPTION**

At 2042 hours on November 25, 2006 with Susquehanna Unit 1 in Mode 1 at 100%, the reactor (EIIS Code: AC) automatically scrammed as a result of a turbine (EIIS Code: TA) trip in response to a main generator (EIIS Code: TB) lockout. The main generator exciter (EIIS Code: TL) voltage regulation circuit did not positively respond to changes to the offsite grid which resulted in a loss of main generator field, thus causing the lockout. Investigation suggests that improper active/reactive current compensator (ARCC) settings in the automatic voltage regulation system were a probable contributor to this shutdown. The improper compensator settings, "tributable to a simple knowledge deficiency, were also believed to have played a significant role in a similar shutdown that occurred on Susquehanna Unit 2 in June 2005. Investigation has also identified that a decision to forego modification of the automatic voltage regulators in a manner described in GE TIL 961-3, may also have contributed to the inability of Susquehanna's units to adequately respond to the grid disturbances.

All control rods inserted and all safety systems responded as designed in response to the automatic scram. Immediately following the scram, five Safety Relief Valves (EIIS Code: SB) opened and then properly reseated. Both Reactor Recirculation pumps (EIIS Code: AD) tripped as expected in response to the pressure transient. The Main Steam (EIIS Code: SB) Bypass Valves were subsequently able to control reactor pressure. Reactor water level dropped to approximately 13 inches and was readily restored to the normal level of 35 inches by the Feedwater system (EIIS Code: SJ). Several balance of plant systems were impacted by the generator voltage perturbation but there were no unusual challenges to the station's safety-related electrical systems. There were no challenges to Containment (EIIS Code: NH) or evidence of fuel failure as a result of this event. Unit 1 was returned to service on November 29, 2006 with the Unit 1 Main Generator Voltage Regulator in manual. This situation is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an unplanned actuation of a system designed to mitigate the consequences of a significant event. This event did not produce adverse consequences to the health and safety of the public.

### **CAUSE OF EVENT**

Less than adequate tuning of the active / reactive current compensator (ARCC) in the automatic voltage regulation system resulted in undesirable interactions between the Susquehanna Units during the grid disturbance experienced on November 25, 2006. The ARCC settings on both Susquehanna Unit 1 and Unit 2 have not been optimized for the current plant configuration. The function of the ARCC circuitry is to control the automatic voltage regulator such that the generator terminal voltage is compensated for the reactive losses between the generator and the desired control point inside the generator's step-up transformers. The high settings of the ARCC on both Susquehanna's Units may have caused the regulation points for Unit 1 and Unit 2 to become too closely aligned. The interaction of the automatic voltage regulators of both units led to the over excitation of one unit and the loss of excitation of the other unit. When considering both the June 2005 scram and this scram, it appears that the unit operating with the higher generator field current after the grid transient would survive the transient. Investigation has revealed that PPL Susquehanna, LLC relies heavily on the knowledge and expertise of electrical distribution personnel when establishing ARCC settings. In order to reduce the reliance on those company entities that are not directly responsible for the operation of Susquehanna, corrective actions will be established to ensure appropriate personnel clearly understand generator control and protective schemes.

GE Technical Information Letter (TIL) 961-3 has not been implemented at Susquehanna. Because, the voltage regulation system design at Susquehanna was considered adequate, it was felt that implementation of TIL 961-3 could only provide enhancement. It is now believed that implementation of TIL 961-3 could help the excitation system recover from disturbances that drive generator excitation low. An evaluation will be performed to determine if implementation of TIL 961-3 is prudent for Susquehanna.

With the causal items described above, PPL Susquehanna, LLC believes that two important factors have been identified which have contributed to the overall event. At the root of these suggested contributors to the shutdown, it has become apparent that there is a lack of sufficient, in-house understanding of the automatic voltage regulator response to a changing grid configuration. Additional planned evaluation could produce further insight into the dynamics surrounding this situation.

(1-2001)

#### NRC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

		. • , –	,		
1. FACILITY NAME	2. DOCKET		6. LER NUMBER		3. PAGE
Susquehanna Steam Electric Station – Unit 1	05000387	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2.25.2
·	03000387	2006 -	- 006	- 00	3 OF 3

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

# **ANALYSIS / SAFETY SIGNIFICANCE**

## Actual Consequences:

On November 25, 2006, a grid disturbance led to a loss of field event on the Unit 1 Main Generator. The loss of the Unit 1 Main Generator field led to actuation of the Unit 1 bus lockout relays, a Unit 1 Main Turbine trip, and a Unit 1 Reactor Scram. All safety systems operated as expected. The reactor reached Operating Mode 3 in a stable condition.

#### Potential Consequences:

Challenges to nuclear safety can result from equipment failure or human errors during recovery of the reactor to normal shutdown conditions. The potential consequence results in a negligible increase in the probabilistic risk to the health and safety of the public.

## **CORRECTIVE ACTIONS**

The following corrective actions have been completed:

- Temporary monitoring equipment was installed on both the Unit 1 and Unit 2 auto voltage regulators.
- Main Generator stability tuning and minimum excitation limit adjustments were completed.
- Until planned corrective actions are sufficiently completed, the Unit 1 Main Generator Voltage Regulator is being maintained in manual to ensure continued station operation during grid disturbances.

#### The following corrective actions are planned:

- Training and/or processes will be developed and implemented to ensure appropriate PPL Susquehanna, LLC personnel understand generator control and protection schemes.
- Appropriate active / reactive current compensator (ARCC) setting changes will be established and implemented.
- General Electric Technical Information Letter 961-3 will be re-evaluated and implemented as appropriate. (Full or partial implementation of TIL 961-3 may enhance the unit's ability to respond correctly to grid disturbances.)

## **ADDITIONAL INFORMATION**

## Failed Components Information:

None

## Past Similar Events:

Docket No. 50-388 LER 2005-005-00 and LER 2005-005-01

NRC FORM 366A (1-2001)